



Installation Instructions

1. Load the software:
 - a. Copy files to your hard drive
 - b. Start WinHost installation by running the setup.exe file
 - c. Follow on-screen installation instructions
2. When installation is complete, connect the detector via the RS485 harness
3. Run the software which is now accessible via the Start menu
4. Select appropriate COM port, as detailed in section 4.2 of the user guide
5. The main software screen will now appear.

It is recommended to read the user guide fully before using the software.